



ZyXEL NBG6515
V1.00(AAXS.1)C0
Release Notes

Date: Dec. 18, 2015

Supported Platforms:

ZyXEL NBG6515

Limitation:

1. It is suggested to reset default settings after upgrading firmware.
2. NBG6515 allows only single user to login the web GUI at one time.

Note:

1. Default LAN IP: 192.168.1.1 (router mode)/ 192.168.1.2 (AP and repeater modes)
2. Default Password: 1234

Versions:

Firmware version: V1.00(AAXS.1)C0

2.4G WLAN code version: mt7620_wifi2720_all_dpa_20140820

5G WLAN code version: mt7610e_wifi3003_dpa_20130301

Modifications in V1.00 (AAXS.1)C0 | 2015/12/18:

1. [BUGFIX] eITS Ticket #151000291 NBG6515: Packet Statistics incorrect "Tx kb/s" and "Rx kb/s" data.
2. [BUGFIX] eITS Ticket #151000379 NBG6515: zyxel.setup issue.
3. [BUGFIX] eITS Ticket #151000633 NBG6515: unstable 2.4GHz radio.
4. [BUGFIX] eITS Ticket #151000800 NBG6515: Online – upgrade firmware sometime doesn't work.
5. [BUGFIX] eITS Ticket #151000799 NBG6515: DLNA doesn't work with SMART TV.
6. [BUGFIX] eITS Ticket #151000380 NBG6515: FTP cannot access from wan.
7. [BUGFIX] eITS Ticket #151000631 NBG6515: WebGUI becomes unresponsive for all during torrent traffic from WLAN client.



8. [BUGFIX] Symptom: WiFi-5GHz: Some apple devices cannot connect to DUT by WiFi 5G and always pop-up a warning message with "Incorrect password for "WiFi_5G_SSID".
9. [Feature Changed] Change eaZy123 to Responsive GUI
10. [Feature Changed] Change WPS behavior to be concurrent

Modifications in V1.00 (AAXS.0)C0 | 2015/06/10:

1. First release